

GRANT COUNTY

Planning Unit 032: AML Printout #556: T132N, R90W, Section 2, SE

Additional Legal Location: SE, SW

Name: Buchanan Mine (aka Eastman Mine) Owner: No data

Category: Commercial/local

Type: Strip (surface)

Overburden:	Coal Seam:	Thickness Mined:	Source:
No data (outcrop)	2-6 ft.	No data (stripped)	Leonard et al.:1925

Cultural Resource Site Numbers Not formally recorded

Basic Data (excerpted from primary sources):

Production statistics were noted for only one year for this mine. It is not known when the mine began operations or when it ceased operations, since it is not listed as a new mine in 1923, and reports from following years do not indicate that the mine closed.

Descriptive information pertaining to this mine is included in:

[source:year (pages)]

WCB Map:1923

Notes:

According to the 1923 WCB map, a mine named "Eastman Mine" was located at T132N, R90W, Section 2, SE, SW. No listings were noted for an Eastman Mine in SEBR or CMID reports; however, a Buchanan Mine (superintendent W.B. Buchanan) was noted. Since the superintendent of the Eastman Mine, according to the WCB (1923) map, also was W.B. Buchanan, the Buchanan Mine has been included with this Planning Unit and AML location.

Sources (primary and secondary):

CMID:see table, next page, for appropriate year
Leonard et al.:1925(33)
WCB:1923

Mine: Buchanan Mine (aka Eastman Mine)

Planning Unit: 032
AML Number: 556

Year	Days Operated	Employees	Price Per Ton	Tons Produced	Tons Local Trade	Tons Shipped	Owner or Superintendent*
1923	60	no data	1.75	300	300	none	W.B. Buchanan**

*Unless otherwise indicated, name listed is that of owner.

**Individual was superintendent of the mine; owner not listed.
