

**HETTINGER COUNTY**

Planning Unit 028: AML Printout # 50: T134N, R95W, Section 10, SW, NE

Additional Legal Location: Section 10, SW

Name:

Owner:

Switzer Coal Mine

Presley Switzer

Category: Commercial/local

Type: Strip (surface)

Overburden:	Coal Seam:	Thickness Mined:	Source:
7-21 ft.	9 ft.	9 ft.	SEBR:1918
15-20 ft.	8 ft.	No data	Leonard et al.:1925

Cultural Resource Site Number: Not formally recorded

Basic Data (excerpted from primary sources):

This mine is not listed as a new mine in 1916 and it may have been in operation prior to that time. The mine is not listed as closed in 1917; however, no further listings were noted for the mine. It is not known if the mine ceased operations or ceased reporting following 1917.

Descriptive Information pertaining to this mine is included in:

[source:year(pages)]

SEBR:1918(146)

Notes:

The Rogers Mine also is located at this Planning Unit and AML location.

It should be noted that the overburden, coal seam, and area mined figures taken from Leonard et al. (1925) and listed above are in direct reference to the Rogers Mine; however, since both mines apparently were located in Section 10, SW, these figures have been provided in relation to the Switzer Mine as well.

Sources (primary and secondary):

Leonard et al.:1925(92)

SEBR:see table, next page, for appropriate years

Mine: Switzer Coal Mine

Planning Unit: 028

AML Number: 50

---

---

Year	Days Operated	Employees	Price Per Ton	Tons Produced	Tons Local Trade	Tons Shipped	Owner or Superintendent
1916	no data	no data	no data	no data	no data	no data	Presley Switzer
1916	"not operated"						
1917	120	2	1.60	800	yes	no	Presley Switzer

---

\*Unless otherwise indicated, name listed is that of owner.

\*\*Individual was superintendent of the mine; owner not listed.