

MORTON COUNTY

Planning Unit 045: AML Printout #426: T139N, R85W, Section 7, SW

Additional Legal Location: No part section

Name: Owner:
New Salem Coal Mine No. 1 No data

Category: No data

Type: Underground, shaft

Overburden:	Coal Seam:	Thickness Mined:	Source:
50 ft.	15 ft. 4 in.	No data	Bureau of Mines:1948

Cultural Resource Site Number: Not formally recorded

Basic Data (excerpted from primary sources):

Bureau of Mines (1948), reporting information compiled in 1920, indicates that the New Salem No. 1 Mine was located at T139N, R85W, Section 7. No CMID listings or other information was noted about a New Salem No. 1 Mine, nor was any information noted that would relate this mine name to other mines located in Section 7.

Descriptive information pertaining to this mine is included in:

[source:year(pages)]

Not applicable

Notes:

The Kramer and possibly Kramer & Kiesel/Kiesel coal mine(2) and the Consolidated Lignite Coal Co. also are located at this Planning Unit and AML location.

Sources (primary and secondary):

Bureau of Mines:1948(81)